

# NEC 2400 ICS Rel J 5.8 PBX with CallManager using 2621XM-E1 PRI as MGCP Gateway

This application note illustrates connectivity for NEC 2400 ICS Rel J 5.8 PBX with CallManager using 2621XM-E1 PRI as MGCP Gateway.

## Introduction

The network topology diagram presented in [Figure 1](#) illustrates the test set-up for end-to-end interoperability with the Cisco CallManager connected to the PBX via 2621XM-E1 PRI link as MGCP Gateway.


Key test environment parameters:

- Connectivity is achieved by using the PRI EURO protocol type on the MGCP gateway and NEC/ETSI switch type on the NEC 2400 PBX. Though the NEC 2400 can be configured as either NETWORK (Master) or USER (Slave) side, this is not recommended and the NEC TAC center will not resolve a case presented with NEC set as NETWORK side.
- Calling Name delivery and presentation features are not supported by the NEC 2400 PBX.
- CCM does not send "Connected Number" information in the CONNECT message back to PBX.



## Network Diagram

Figure 1  
Network Test Topology



## Limitations

### Calling Name and Number Feature

Calling Name delivery and presentation feature are not supported by the NEC 2400 ICS PBX.

When calling from Cisco 7960 IP phone to NEC digital phone, both phones display the Number after the call is answered as expected.

When calling from NEC digital phone to Cisco 7960 IP phone, the Cisco IP phone displays Calling Number when the call is answered. NEC phone however does NOT get updated when the call is answered. It displays the numbers being dialed instead (i.e. Access Code + extension number). It was verified using an ISDN protocol analyzer that the CCM was not sending "Connected Number" information in the CONNECT message back to PBX.

## System Components

### Hardware Requirements

Cisco Hardware:

- Cisco 2621XM with 2MFT-E1 port
- Cisco Cat6K switch



- Cisco CM 3.2

NEC 2400 ICS PBX:

- Hardware: PA-30PRTB

### Software Requirements

- PBX Software Release J 5.8.
- Cisco CM 3.2

### Feature

Key features supported:

- Calling/Called Number Identification

Key features not supported:

- Updating Connected Number
- Calling/Called Name

### Configuration

Sequence of configuration tasks:

1. [NEC 2400 ICS Configuration](#)
2. [Route \(ARTD\) Configuration](#)
3. [Cisco CallManager Configuration](#)
4. [ISDN PRI Configuration](#)

### NEC 2400 ICS Configuration

The NEC requires a substantial amount of programming and circuit card switch settings to properly install E1 PRI. It is beyond the scope of this document to provide the entire configuration, therefore the NEC information below is mostly helpful for NEC techs. If further assistance is required, the entire configuration of our lab PBX can be found in EDCS document # EDCS-207455. The EDCS document provides the programs required for E1 ISDN circuit setup, all the switch settings for all cards on our Lab NEC and fairly complete configuration listings (*List Ups*).

Note: The switch settings and software references in the EDCS document assume a familiarity with the NEC 2400. It is highly recommended to have a NEC ISDN certified technician setup the NEC portion.

Configure in the following sequence:

1. Install circuit card.
2. Configure all software.

Table 1 Circuit Card Configuration (PA-30PRTB)t

Switch	Position	Description	Setting
SW00		Make Busy	Down
SW01	0	All Channel Make Busy	Off



Table 1 Circuit Card Configuration (PA-30PRTB)t

Switch	Position	Description	Setting
	1	External Loop Back	Off
	2	Internal Loop Back	Off
	3	Dch Handler Make Busy	Off
<b>SW02 (SENSE - Rotary)</b>		1 = AT&T 2 = Australia 3 = NTT Japan 4 = NEC/ETSI 5 = AT&T 6 = INS A = Q.SIG	4
<b>SW10</b>	Jumper	Off = Coax On = Twisted Pair	On
<b>SW11</b>	Jumper	Off = Coax On = Twisted Pair	On
<b>SW12</b>	Jumper	Off = Coax On = Twisted Pair	On
<b>SW13</b>	1	On = PAD ROM Special Version Off = PAD ROM Standard Version	Off
	2	On = ISDN BUS Not Used Off = ISDN BUS Used	On
	3	Not Used	Off
	4	Not Used	Off
<b>SW14</b>	1	On = CCITT Signaling Off = CEPT Signaling	On
	2	On = Alarm Release: 2sec (Aus) Off = Alarm Release 15 Sec.	On
	3	PAD	On
	4	PAD	On
	5	PAD	On
	6	PAD	On
	7	PAD	On
	8	Fixed Off	Off
<b>SW15</b>	1	Loopback Pattern Off = Loopback inhibited	Off



Table 1 Circuit Card Configuration (PA-30PRTB)t

Switch	Position	Description	Setting
	2	Loopback Pattern Off = Loopback inhibited	Off
	3	Loopback Pattern Off = Loopback inhibited	Off
	4	Loopback Pattern Off = Loopback inhibited	Off
	5	TS16 Control: On = Data Through (CCIS/ ISDN) Off = Signaling	On
	6	On = No CRC4 Off = CRC4	Off
	7	Firmware (CCITT/China/ Thailand/Aux)	On
	8	Firmware (CCITT/China/ Thailand/Aux)	On
<b>SW16</b>	1	Fixed Off	Off
	2	Fixed Off	Off
	3	All "1" Supervision On = To be controlled Off = Not to be controlled	Off
	4	On = Dch User Side Off = Dch Network Side	On
	5	On = Dch NegativeLogic Off = Dch Positive Logic	Off
	6	On = Dch Packet Service On Off = Dch Packet Service Off	Off
	7	Fixed Off	Off
	8	Fixed Off	Off





38 FA 0 0 0 0 0

[LRTD] CISCO TEST FACILITY 02/05/10 PAGE: 6

\* ROUTE CLASS DATA LIST \*

CDN FUNCTION	R O U T E N U M B E R				
	11	12	13	14	15
39 BC	0	0	0	0	0
40 TCM	0	0	0	0	0
41 TDMQ	0	0	0	0	0
42 TRSC	0	0	0	0	0
43 BT	0	1	0	1	1
44 PRV	0	0	0	0	0
45 A/D	0	1	1	1	1
46 CW	0	0	0	0	0
47 TPQ	0	0	0	0	0
48 BL	0	0	0	0	0
49 TRKS	0	1	1	0	0
50 DPLY	0	1	1	1	1
51 ACD	0	0	0	0	0
52 2W/4W	1	0	0	0	0
53 FAAT	0	0	0	0	0
54 GW	0	0	0	0	0
55 TCMA	0	0	0	0	0
56 SMDR3	0	0	0	0	0
57 HDT	0	0	0	0	0
58 CD	0	0	0	0	0
59 CCH	0	0	0	0	0
60 TC/EC	0	0	0	0	0
61 IRE	0	0	0	0	0
62 SCR	0	0	0	0	0
63 LYER1	0	1	1	1	1
64 NET	0	1	0	0	0
65 INT	0	4	4	4	4
66 DC	0	4	4	4	4
67 HKS	0	0	0	0	0
68 SCF	0	0	0	0	0
69 SMDR4	0	0	0	0	0



## Cisco CallManager Configuration

### MGCP 2621XM-E1 Gateway Configuration

Cisco CallManager 3.2 Administration - MGCP Configuration - Microsoft Internet Explorer

File Edit View Favorites Tools Help

Back Forward Stop Home Search Favorites History Print Address -4454-B075-E45E2BACCD1} Go Links

System Route Plan Service Feature Device User Application Help

# Cisco CallManager Administration

For Cisco IP Telephony Solutions

CISCO SYSTEMS

## MGCP Configuration

[Back to Find/List Gateways](#)

**Product: Cisco 26XX**  
**MGCP : MGCP\_2621XM**

Status: Ready

Update Delete Reset Gateway Cancel Changes

MGCP Domain Name\* MGCP\_2621XM

Description 2621XM MGCP Gateway

Cisco CallManager Group\* Default

Installed Voice Interface Cards		Endpoint Identifiers	
Module in Slot 1	NM-HDV		
Sub-Unit 0	VVIC-2MFT-E1	(1/0) e1	(1/1) e1

### Product Specific Configuration

Global ISDN Switch Type EURO

Switchback Timing\* Graceful

Switchback uptime-delay (min) 10

Switchback schedule (hh:mm) 12:00

\* indicates required item

[Back to Find/List Gateways](#)

Local intranet





## ISDN PRI Configuration

Cisco CallManager 3.2 Administration - Gateway Configuration - Microsoft Internet Explorer

File Edit View Favorites Tools Help

Back Forward Stop Home Search Favorites History Print Address: -4454-8075-E45E28ACCCD1 Go Links

System Route Plan Service Feature Device User Application Help

**Cisco CallManager Administration**  
For Cisco IP Telephony Solutions

**Gateway Configuration**

[Back to MGCP Configuration](#)  
[Back to Find/List Gateways](#)

**Product : Cisco 26XX**  
**Gateway : S1/DS1-0@MGCP\_2621XM**  
**Device Protocol: Digital Access PRI**  
**Registration: Registered with Cisco CallManager 10.1.1.2**  
**IP Address: 10.1.1.220**

Status: Update completed.

End-Point Name*	S1/DS1-0@MGCP_2621XM
Description	S1/DS1-0@MGCP_2621XM
Device Pool*	Default
Media Resource Group List	< None >
Network Hold Audio Source	< None >
User Hold Audio Source	< None >
Calling Search Space	< None >
Location	< None >
Load Information	
Channel Selection Order*	Top Down
Protocol Side*	Network
Caller ID DN	
Calling Party Selection*	Originator
Channel IE Type*	Use Number when 1B

Reset succeeded. Local intranet



Cisco CallManager 3.2 Administration - Gateway Configuration - Microsoft Internet Explorer

File Edit View Favorites Tools Help

Back Forward Stop Home Search Favorites History Print Address -4454-B075-E45E28ACCCD1} Go Links >>

MCDN Channel Number Extension Bit Set to Zero**	<input type="checkbox"/>
Interface Identifier Present**	<input type="checkbox"/>
Interface Identifier Value**	<input type="text" value="0"/>
Display IE Delivery	<input checked="" type="checkbox"/>
Redirecting Number IE Delivery - Outbound	<input checked="" type="checkbox"/>
Redirecting Number IE Delivery - Inbound	<input type="checkbox"/>
Delay for first restart (1/8 sec ticks)	<input type="text" value="32"/>
Delay between restarts (1/8 sec ticks)	<input type="text" value="4"/>
Num Digits*	<input type="text" value="23"/>
Sig Digits	<input checked="" type="checkbox"/>
Prefix DN	<input type="text"/>
Presentation Bit*	<input type="text" value="Allowed"/>
Called party IE number type unknown*	<input type="text" value="Cisco CallManager"/>
Calling party IE number type unknown*	<input type="text" value="Cisco CallManager"/>
Called Numbering Plan*	<input type="text" value="Cisco CallManager"/>
Calling Numbering Plan*	<input type="text" value="Cisco CallManager"/>
PRI Protocol Type*	<input type="text" value="PRI EURO"/>
Inhibit restarts at PRI initialization	<input checked="" type="checkbox"/>
Enable status poll	<input type="checkbox"/>
Number of digits to strip*	<input type="text" value="0"/>
Network Locale	<input type="text" value="&lt; None &gt;"/>
Setup non-ISDN Progress Indicator IE Enable****	<input type="checkbox"/>

**Product Specific Configuration**

Reset succeeded. Local intranet



Cisco CallManager 3.2 Administration - Gateway Configuration - Microsoft Internet Explorer

File Edit View Favorites Tools Help

Back Forward Stop Home Search Favorites History Print Address [-4454-8075-E45E28ACCCD1}](#) Go Links

### Product Specific Configuration

Line Coding*	HDB3
Framing*	CRC4
Clock*	External

\* indicates required item  
\*\* applicable to DMS-100 protocol only  
\*\*\* applicable to DMS-100 protocol and DMS-250 protocol only  
\*\*\*\* may be required to force ringback from some PBXs

[Back to MGCP Configuration](#)  
[Back to Find/List Gateways](#)

Reset succeeded. Local intranet



## Route Pattern Configuration

Cisco CallManager 3.2 Administration - Route Pattern Configuration - Microsoft Internet Explorer

File Edit View Favorites Tools Help

Back Forward Stop Home Search Favorites History Address -4982-A802-A797EDBC5B55 Go Links

System Route Plan Service Feature Device User Application Help

**Cisco CallManager Administration**  
For Cisco IP Telephony Solutions

**CISCO SYSTEMS**

# Route Pattern Configuration

[Add a New Route Pattern](#)  
[Back to Find/List Route Patterns](#)

**Route Pattern: 7.XXXX**

Status: Ready  
Note: Any update to this route pattern automatically resets the associated gateway/route list

Copy Update Delete Cancel Changes

### Pattern Definition

Route Pattern*	7.XXXX
Partition	< None >
Numbering Plan*	North American Numbering Plan
Route Filter	< None >
Gateway/Route List*	S1/DS1-0@MGCP_2621XM (Edit)
Route Option	<input checked="" type="radio"/> Route this pattern <input type="radio"/> Block this pattern
<input checked="" type="checkbox"/> Provide Outside Dial Tone	<input type="checkbox"/> Urgent Priority

### Calling Party Transformations

Use Calling Party's External Phone Number Mask

Calling Party Transform Mask

Prefix Digits (Outgoing Calls)

### Called Party Transformations

Discard Digits

Called Party Transform Mask

Prefix Digits (Outgoing Calls)

\* indicates required item.

Done Local intranet



## Appendix A

### Cisco CallManager Software Release



### NEC 2400 ICS Software Release

#### Software Release:

VERSION	ISSUE	DATE	
J	05.80	00/06/20	Generic
F	01.00	96/04/26	Boot ROM



## Cisco 2621XM Gateway Configuration

```
MGCP_2621XM#sh version
Cisco Internetwork Operating System Software
IOS (tm) C2600 Software (C2600-JS-M), Version 12.2(10.7)T2, MAINTENANCE INTERIM
SOFTWARE
TAC Support: http://www.cisco.com/tac
Copyright (c) 1986-2002 by cisco Systems, Inc.
Compiled Wed 05-Jun-02 12:20 by ccai
Image text-base: 0x8000809C, data-base: 0x819781E4
```

```
ROM: System Bootstrap, Version 12.2(7r) [cmong 7r], RELEASE SOFTWARE (fcl)
```

```
MGCP_2621XM uptime is 1 hour, 1 minute
System returned to ROM by reload
System image file is "flash:c2600-js-mz.122-10.7.T2"
```

```
cisco 2621XM (MPC860P) processor (revision 0x100) with 124928K/6144K bytes of me
mory.
```

```
Processor board ID JAD06110FE9 (4191950531)
M860 processor: part number 5, mask 2
Channelized E1, Version 1.0.
Bridging software.
X.25 software, Version 3.0.0.
SuperLAT software (copyright 1990 by Meridian Technology Corp).
TN3270 Emulation software.
Primary Rate ISDN software, Version 1.1.
2 FastEthernet/IEEE 802.3 interface(s)
31 Serial network interface(s)
2 Channelized E1/PRI port(s)
32K bytes of non-volatile configuration memory.
49152K bytes of processor board System flash (Read/Write)
```

```
Configuration register is 0x2102
```

```
MGCP_2621XM#
```

```
MGCP_2621XM#sh diag
```

```
Slot 0:
```

```
C2621XM 2FE Mainboard Port adapter, 2 ports
Port adapter is analyzed
Port adapter insertion time unknown
EEPROM contents at hardware discovery:
Hardware Revision      : 1.0
PCB Serial Number     : JAD06110FE9 (4191950531)
Part Number           : 73-7754-02
RMA History           : 00
RMA Number            : 0-0-0-0
Board Revision        : A0
Deviation Number      : 0-0
EEPROM format version 4
EEPROM contents (hex):
0x00: 04 FF 40 03 6D 41 01 00 C1 18 4A 41 44 30 36 31
0x10: 31 30 46 45 39 20 28 34 31 39 31 39 35 30 35 33
0x20: 31 29 82 49 1E 4A 02 04 00 81 00 00 00 00 42 41
0x30: 30 80 00 00 00 00 FF FF FF FF FF FF FF FF FF
0x40: FF FF FF FF FF FF FF FF FF FF FF FF FF FF FF
0x50: FF FF FF FF FF FF FF FF FF FF FF FF FF FF FF
```



```
0x60: FF FF FF FF FF FF FF FF FF FF FF FF FF FF FF
0x70: FF FF FF FF FF FF FF FF FF FF FF FF FF FF FF
```

Slot 1:

```
High Density Voice Port adapter
Port adapter is analyzed
Port adapter insertion time unknown
EEPROM contents at hardware discovery:
Hardware Revision      : 1.0
Top Assy. Part Number  : 800-03567-01
Board Revision        : A0
Deviation Number      : 0-0
Fab Version           : 02
PCB Serial Number     : JAB033906YA
RMA Test History      : 00
RMA Number            : 0-0-0-0
RMA History           : 00
EEPROM format version 4
EEPROM contents (hex):
0x00: 04 FF 40 00 CC 41 01 00 C0 46 03 20 00 0D EF 01
0x10: 42 41 30 80 00 00 00 00 02 02 C1 8B 4A 41 42 30
0x20: 33 33 39 30 36 59 41 03 00 81 00 00 00 00 04 00
0x30: FF FF FF FF FF FF FF FF FF FF FF FF FF FF FF
0x40: FF FF FF FF FF FF FF FF FF FF FF FF FF FF FF
0x50: FF FF FF FF FF FF FF FF FF FF FF FF FF FF FF
0x60: FF FF FF FF FF FF FF FF FF FF FF FF FF FF FF
0x70: FF FF FF FF FF FF FF FF FF FF FF FF FF FF FF
```

VIC Slot 0:

```
E1 (2 Port) Multi-Flex Trunk WAN Daughter Card
Hardware revision 1.0          Board revision B0
Serial number 25028793        Part number 800-04479-02
Test history 0x0              RMA number 00-00-00
Connector type PCI
EEPROM format version 1
EEPROM contents (hex):
0x20: 01 23 01 00 01 7D E8 B9 50 11 7F 02 00 00 00 00
0x30: 58 00 00 00 01 02 16 00 FF FF FF FF FF FF FF FF
```

```
HDV firmware: Compiled Thu 27-Dec-01 13:17 by miriyala
HDV memory size 524280 heap free 171117
```

MGCP\_2621XM#

MGCP\_2621XM#sh controllers e1 1/0

E1 1/0 is up.

Applique type is Channelized E1 - balanced

No alarms detected.

alarm-trigger is not set

Version info Firmware: 20020306, FPGA: 11

Framing is CRC4, Line Code is HDB3, Clock Source is Line.

Data in current interval (56 seconds elapsed):

0 Line Code Violations, 0 Path Code Violations

0 Slip Secs, 0 Fr Loss Secs, 0 Line Err Secs, 0 Degraded Mins

0 Errored Secs, 0 Bursty Err Secs, 0 Severely Err Secs, 0 Unavail Secs



```
MGCP_2621XM#
MGCP_2621XM#sh run
Building configuration...

Current configuration : 1381 bytes
!
version 12.2
service timestamps debug uptime
service timestamps log uptime
no service password-encryption
!
hostname MGCP_2621XM
!
!
voice-card 1
!
ip subnet-zero
!
!
!
isdn switch-type primary-net5
!
!
voice call carrier capacity active
!
!
!
!
!
!
!
!
!
!
ccm-manager mgcp
ccm-manager music-on-hold
ccm-manager config server 10.1.1.2
ccm-manager config
fax interface-type fax-mail
mta receive maximum-recipients 0
!
controller E1 1/0
  pri-group timeslots 1-31 service mgcp
!
controller E1 1/1
!
!
!
!
interface FastEthernet0/0
  ip address 10.1.1.220 255.255.255.0
  duplex auto
  speed auto
!
interface FastEthernet0/1
  no ip address
  shutdown
  duplex auto
```






```
speed auto
!
interface Serial1/0:15
  no ip address
  no logging event link-status
  isdn switch-type primary-net5
  isdn protocol-emulate network
  isdn incoming-voice voice
  isdn bind-13 ccm-manager
  no cdp enable
!
ip classless
no ip http server
ip pim bidir-enable
!
!
!
!
call rsvp-sync
!
voice-port 1/0:15
!
mgcp
mgcp call-agent 10.1.1.2 service-type mgcp version 0.1
mgcp dtmf-relay voip codec all mode out-of-band
mgcp modem passthrough voip mode nse
mgcp package-capability rtp-package
no mgcp timer receive-rtcp
mgcp sdp simple
!
mgcp profile default
!
dial-peer cor custom
!
!
!
dial-peer voice 1015 pots
  application mgcpapp
  port 1/0:15
!
!
line con 0
line aux 0
line vty 0 4
  login
line vty 5 15
  login
!
!
end

MGCP_2621XM#
```



## Test Configuration

Figure 2  
Test Topology



As shown in the diagram above, an NEC 2400 ICS PBX was connected via an ISDN E1 PRI link to a Cisco 2621XM-E1 Gateway, which in turn, was connected to an Ethernet switch. The interoperability testing involved Layers 1, 2 and 3 on the ISDN PRI link between a Cisco 2621XM-E1 and the PBX.

### Layers 2 & 3 (Q.921 and Q.931)

Layer 2 and 3 packet exchanges were monitored using an Acacia Clarinet protocol analyzer, bridged across the PRI link in high impedance mode.

Layer 2 Q.921 packets were monitored to ensure that each PBX/2621XM-E1 software configuration properly exchanged SABME/UA packets to initialize the ISDN link, and then RR packets were exchanged every 30 seconds.

Layer 3 Q.931 packets were monitored to ensure that the appropriate call setup/teardown packets were exchanged for each configuration, and that the SETUP packets contained the mandatory Information Elements with the necessary details, as well as optional IEs such as Calling Name and Number.

Telephone calls were made end-to-end in both directions through the Cisco 2621XM-E1 Gateway, and a check was made to ensure that there was an audio path in both directions for each call.



## User/Network Settings

The Cisco 2621XM-E1 Gateway with ISDN protocol type setting of PRI EURO supports both protocol sides by selecting “Network/User” in the Protocol Side field when configuring the Gateway via CCM. The NEC 2400 ICS PBX supports “USER” protocol side.

## Appendix B

### Test Results

Testing was performed by Test Engineer(s): Samir Batio, June 12, 2002

### Test Setup

Test configuration:

- PBX1 configured as ETSI, emulates User
- Cisco 2621XM-E1 Gateway configured as PRI EURO, emulates Network

Table 2 Test Setup Switch and Gateway Settings

NEC 2400 ICS Switch-type / Protocol-side Setting	Cisco 2621XM-E1 ISDN Protocol-type/ Protocol-side Setting
ETSI / User	PRI EURO / Network

Table 3 Basic Calls: (Enbloc Sending)

Calls Made	Call Comp?	“ Calling Number” Passed to Final Destination?	“ Calling Name” Passed to Final Destination?	“ Called Number” Passed to Orig. Side?	“ Called Name” Passed to Orig. Side?	Notes
Phone A to Phone C	Yes	Yes	No	No <sup>1</sup>	No	<sup>2</sup>
Phone C to Phone A	Yes	Yes	No	Yes	No	

1. CCM does not support sending “Connected Number” information in the connect message back to PBX.

2. The NEC 2400 with switch-type setting of ETSI for the PRI interface does not support “Calling Name” presentation feature.



Table 4 Basic Calls: (FXS Port)

Calls Made	Call Comp?	" Number" Displayed on the digital phone?	" Name" Displayed on the digital phone?	Notes
Phone E to Phone A	N/A			
Phone A to Phone E	N/A			
Phone E to Phone C	N/A			
Phone C to Phone E	N/A			

Table 5 Basic Calls with Overlap Sending/Receiving: (check trace to verify Overlap mode)

Calls Made	Call Comp?	" Calling Number" Passed to Final Destination?	" Calling Name" Passed to Final Destination?	" Called Number" Passed to Orig. Side?	" Called Name" Passed to Orig. Side?	Notes
Phone A to Phone C	N/A					1
Phone C to Phone A	N/A					

1. NEC 2400 ICS PBX does not support Overlap sending/Receiving mode.

Table 6 Call Transfers: (Supervised Local Transfers)

Calls Made	Call Comp?	Orig. " Calling Number" displayed on Final Dest. phone?	Orig. " Calling Name" displayed on Final Dest. phone?	" Called Number" display on Orig. phone updated after transfer?	" Called Name" display on Orig. phone updated after transfer?	Notes
Phone C to Phone A Xfr to Phone B	Yes	Yes	No	No	No	
Phone A to Phone C Xfr to Phone D	Yes	Yes	No	No	No	

Table 7 Call Conferencing (Local)

Calls Made	Call Comp?	" Calling Number" passed to remaining conferee when the conferencing phone drops out?	" Calling Name" passed to remaining conferee when the conferencing phone drops out?	" Connected Number" updated on Orig. Caller phone display when a conferee drops out?	" Connected Name" updated on Orig. Caller phone display when a conferee drops out?	Notes
Phone C to Phone A, Phone A conf Phone B	Yes	(A Drops out) Yes	(A Drops out) No	(A Drops out) No	(A Drops out) No	
Phone C to Phone A, Phone C conf Phone D	Yes	(C Drops out) No	(C Drops out) No	(D Drops out) No	(D Drops out) No	
Phone A to Phone C, Phone C conf Phone D	Yes	(C Drops out) No	(C Drops out) No	(C Drops out) No	(C Drops out) No	
Phone A to Phone C, Phone A conf Phone B	Yes	(A Drops out) No	(A Drops out) No	(B Drops out) No	(B Drops out) No	

Table 8 Call Forward (Local)

Calls Made	Call Comp?	Original "Calling Number" passed to Final Dest.?	Original "Calling Name" passed to Final Dest.?	Forwarding "Called Number" passed to Final Dest.?	Forwarding "Called Name" passed to Final Dest.?	Final dest. "Connected Number" updated at orig. side?	Final dest. "Connected Name" updated at orig. side?	Notes
Phone C to Phone A fwd to Phone B	Yes	Yes	No	No	No	No	No	
Phone A to Phone C fwd to Phone D	Yes	Yes	No	No	No	No	No	



Corporate Headquarters  
Cisco Systems, Inc.  
170 West Tasman Drive  
San Jose, CA 95134-1706  
USA  
www.cisco.com  
Tel: 408 526-4000  
800 553-NETS (6387)  
Fax: 408 526-4100

European Headquarters  
Cisco Systems International BV  
Haarlerbergpark  
Haarlerbergweg 13-19  
1101 CH Amsterdam  
The Netherlands  
www-europe.cisco.com  
Tel: 31 0 20 357 1000  
Fax: 31 0 20 357 1100

Americas Headquarters  
Cisco Systems, Inc.  
170 West Tasman Drive  
San Jose, CA 95134-1706  
USA  
www.cisco.com  
Tel: 408 526-7660  
Fax: 408 527-0883

Asia Pacific Headquarters  
Cisco Systems, Inc.  
Capital Tower  
168 Robinson Road  
#22-01 to #29-01  
Singapore 068912  
www.cisco.com  
Tel: +65 317 7777  
Fax: +65 317 7799

Cisco Systems has more than 200 offices in the following countries and regions. Addresses, phone numbers, and fax numbers are listed on the **Cisco Web site at [www.cisco.com/go/offices](http://www.cisco.com/go/offices)**

Argentina • Australia • Austria • Belgium • Brazil • Bulgaria • Canada • Chile • China PRC • Colombia • Costa Rica • Croatia  
Czech Republic • Denmark • Dubai, UAE • Finland • France • Germany • Greece • Hong Kong SAR • Hungary • India • Indonesia • Ireland  
Israel • Italy • Japan • Korea • Luxembourg • Malaysia • Mexico • The Netherlands • New Zealand • Norway • Peru • Philippines • Poland  
Portugal • Puerto Rico • Romania • Russia • Saudi Arabia • Scotland • Singapore • Slovakia • Slovenia • South Africa • Spain • Sweden  
Switzerland • Taiwan • Thailand • Turkey • Ukraine • United Kingdom • United States • Venezuela • Vietnam • Zimbabwe

All contents are Copyright © 1992-2002, Cisco Systems, Inc. All rights reserved. CCIP, the Cisco Arrow logo, the Cisco Powered Network mark, the Cisco Systems Verified logo, Cisco Unity, Follow Me Browsing, FormShare, Internet Quotient, iQ Breakthrough, iQ Expertise, iQ FastTrack, the iQ logo, iQ Net Readiness Scorecard, Networking Academy, ScriptShare, SMARTnet, TransPath, and Voice LAN are trademarks of Cisco Systems, Inc.; Changing the Way We Work, Live, Play, and Learn, Discover All That's Possible, The Fastest Way to Increase Your Internet Quotient, and iQuick Study are service marks of Cisco Systems, Inc.; and Aironet, ASIST, BPX, Catalyst, CCDA, CCDP, CCIE, CCNA, CCNP, Cisco, the Cisco Certified Internetwork Expert logo, Cisco IOS, the Cisco IOS logo, Cisco Press, Cisco Systems, Cisco Systems Capital, the Cisco Systems logo, Empowering the Internet Generation, Enterprise/Solver, EtherChannel, EtherSwitch, Fast Step, GigaStack, IOS, IP/TV, LightStream, MGX, MICA, the Networkers logo, Network Registrar, Packet, PIX, Post-Routing, Pre-Routing, RateMUX, Registrar, SlideCast, StrataView Plus, Stratum, SwitchProbe, TeleRouter, and VCO are registered trademarks of Cisco Systems, Inc. and/or its affiliates in the U.S. and certain other countries.

All other trademarks mentioned in this document or Web site are the property of their respective owners. The use of the word partner does not imply a partnership relationship between Cisco and any other company. (0206R)