

NEC 2400 ICS PBX with CallManager using 3640-E1 MGCP Gateway

This application note illustrates connectivity for NEC 2400 ICS PBX with CallManager using 3640-E1 MGCP Gateway.

Introduction

The network topology diagram presented in Figure 1 illustrates the test set-up for end-to-end interoperability between the Cisco CallManager connected to the PBX via 3640-E1 link as MGCP Gateway.

Key test environment parameters:

- Calling Name delivery and presentation features are not supported by the NEC 2400 ICS PBX.
- Calling Number is displayed when calling either direction as expected. The Connected Number is not returned by CallManager nor NEC. This was verified using an ISDN protocol analyzer.
- Connectivity is achieved by using the industry standard ETSI protocol.
 Though the NEC 2400 ICS can be configured as either NETWORK (Master) or USER (Slave) side, configuration as NETWORK is not recommended. The NEC TAC center will not resolve a case presented with NEC set as the NETWORK side.




Network Diagram

Figure 1

Network Test Topology

Basic Call Setup End-to-End Configuration



Limitations

Calling Name and Number Feature

- 1. Calling Name delivery and presentation features are not supported by the NEC 2400 ICS PBX.
- 2. Returning the Connected Number in the Connect message is not supported by CallManager nor NEC.

System Components

Hardware Requirements

Cisco Hardware:

- Cisco 3640 Gateway with 2MFT E1 Port
- · Cisco Cat6K switch
- Cisco CallManager 3.2

NEC 2400 ICS PBX:

· Hardware: PA-30PRTB

Software Requirements

• Cisco IOS software releases "c3640-js-mz.122-2.XN"



• PBX Software: VERSION ISSUE DATE

J 05.80 00/06/20 Generic

F 01.00 96/04/26 Boot ROM

• Cisco CallManager 3.2

Feature

Key features supported:

· Calling Number

Key features not supported:

- · Connected Number
- · Calling/Called Name

Configuration

Configuration tasks consist of:

- 1. NEC 2400 ICS Configuration
- 2. Route (ARTD) Configuration
- 3. Cisco ISDN PRI Configuration
- 4. Route Pattern Configuration
- 5. MGCP (3640) Gateway Configuration

NEC 2400 ICS Configuration

The NEC requires a substantial amount of programming and circuit card switch settings to properly install E1 PRI. It is beyond the scope of this document to provide the entire configuration, therefore the NEC information below is mostly helpful for NEC techs. If further assistance is required, the entire configuration of our lab PBX can be found in EDCS document # EDCS-207455. The EDCS document provides the programs required for E1 ISDN circuit setup, all the switch settings for all cards on our Lab NEC and fairly complete configuration listings (*List Ups*).

The switch settings and software references in the EDCS document assume a familiarity with the NEC 2400. It is highly recommended to have a NEC ISDN certified technician setup the NEC portion.

Configure in the following sequence:

- 1. Install circuit card.
- 2. Configure all software.

 Table 1
 Circuit Card Configuration (PA-30PRTB)

Switch	Position	Description	Setting
SW00		Make Busy	Down
SW01	0	All Channel Make Busy	Off
	1	External Loop Back	Off



Table 1 Circuit Card Configuration (PA-30PRTB)

Switch	Position	Description	Setting
	2	Internal Loop Back	Off
	3	Dch Handler Make Busy	Off
SW02 (SENSE - Rotary)		1 = AT&T 2 = Australia 3 = NTT Japan 4 = NEC/ETSI 5 = AT&T 6 = INS A = Q.SIG	4
SW10	Jumper	Off = Coax On = Twisted Pair	On
SW11	Jumper	Off = Coax On = Twisted Pair	On
SW12	Jumper	Off = Coax On = Twisted Pair	On
SW13	1	On = PAD ROM Special Version Off = PAD ROM Standard Version	Off
	2	On = ISDN BUS Not Used Off = ISDN BUS Used	On
	3	Not Used	Off
	4	Not Used	Off
SW14	1	On = CCITT Signaling Off =CEPT Signaling	On
	2	On = Alarm Release: 2sec (Aus) Off = Alarm Release 15 Sec.	On
	3	PAD	On
	4	PAD	On
	5	PAD	On
	6	PAD	On
	7	PAD	On
	8	Fixed Off	Off
SW15	1	Loopback Pattern Off = Loopback inhibited	Off
	2	Loopback Pattern Off = Loopback inhibited	Off



 Table 1
 Circuit Card Configuration (PA-30PRTB)

Switch	Position	Description	Setting
	3	Loopback Pattern Off = Loopback inhibited	Off
	4	Loopback Pattern Off = Loopback inhibited	Off
	5	TS16 Control: On = Data Through (CCIS/ ISDN) Off = Signaling	On
	6	On = No CRC4 Off = CRC4	Off
	7	Firmware (CCITT/China/ Thailand/Aux)	On
	8	Firmware (CCITT/China/ Thailand/Aux)	On
SW16	1	Fixed Off	Off
	2	Fixed Off	Off
	3	All "1" Supervision On = To be controlled Off = Not to be controlled	Off
	4	On = Dch User Side Off = Dch Network Side	On
	5	On = Dch NegativeLogic Off = Dch Positive Logic	Off
	6	On = Dch Packet Service On Off = Dch Packet Service Off	Off
	7	Fixed Off	Off
	8	Fixed Off	Off



Route (ARTD) Configuration

Below are the Route settings found in ARTD. Route 12 is the B channel and Route 13 is the D channel. Please refer to EDCS document # EDCS-207455 for complete details for configuration.



38 FA 0 0 0 0 0


[LRTD] CISCO TEST FACILITY 02/05/10 PAGE: 6

* ROUTE CLASS DATA LIST *


CDN	FUNCTION	 11	R O U T E	N U 1	M B E R 14	 15
39	ВС	0	0	0	0	0
40	TCM	0	0	0	0	0
		0	0	0	0	
41	TDMQ					0
42	TRSC	0	0	0	0	0
43	BT	0	1	0	1	1
44	PRV	0	0	0	0	0
45	A/D	0	1	1	1	1
46	CW	0	0	0	0	0
47	TPQ	0	0	0	0	0
48	BL	0	0	0	0	0
49	TRKS	0	1	1	0	0
50	DPLY	0	1	1	1	1
51	ACD	0	0	0	0	0
52	2W/4W	1	0	0	0	0
53	FAAT	0	0	0	0	0
53	FAAI	U	U	U	U	U
54	GW	0	0	0	0	0
55	TCMA	0	0	0	0	0
56	SMDR3	0	0	0	0	0
57	HDT	0	0	0	0	0
58	CD	0	0	0	0	0
59	CCH	0	0	0	0	0
	TC/EC	0	0	0	0	0
61	IRE	0	0	0	0	0
62	SCR	0	0	0	0	0
63	LYER1	0	1	1	1	1
64	NET	0	1	0	0	0
65	INT	0	4	4	4	4
66	DC	0	4	4	4	4
67	HKS	0	0	0	0	0
68	SCF	0	0	0	0	0
69	SMDR4	0	0	0	0	0



Cisco ISDN PRI Configuration











Route Pattern Configuration





MGCP (3640) Gateway Configuration





Appendix A

CallManager Software Release



NEC Software release:

DISS 02/05/10 16:06 CISCO TEST FACILITY

MM

VERSION ISSUE DATE

J 05.80 00/06/20 Generic

MM


VERSION ISSUE DATE

F_ 01.00 96/04/26 Boot ROM

DISS END 02/05/10 16:07



CallManager Components Release





Cisco 3640 Router Configuration

```
MGCP_3640#sh ver
Cisco Internetwork Operating System Software
IOS (tm) 3600 Software (C3640-JS-M), Experimental Version 12.2(20020124:013600)
[accheung-v122_xn_throttle.build 101]
Copyright (c) 1986-2002 by cisco Systems, Inc.
Compiled Wed 23-Jan-02 17:57 by accheung
Image text-base: 0x60008948, data-base: 0x61608000
ROM: System Bootstrap, Version 11.1(19)AA, EARLY DEPLOYMENT RELEASE SOFTWARE (fc1)
MGCP_3640 uptime is 1 hour, 40 minutes
System returned to ROM by power-on
System image file is "flash:c3640-js-mz"
cisco 3640 (R4700) processor (revision 0x00) with 58368K/7168K bytes of memory.
Processor board ID 10620494
R4700 CPU at 100Mhz, Implementation 33, Rev 1.0
Channelized E1, Version 1.0.
Bridging software.
X.25 software, Version 3.0.0.
SuperLAT software (copyright 1990 by Meridian Technology Corp).
TN3270 Emulation software.
Primary Rate ISDN software, Version 1.1.
2 Ethernet/IEEE 802.3 interface(s)
55 Serial network interface(s)
2 Channelized E1/PRI port(s)
2 Channelized T1/PRI port(s)
2 Voice FXO interface(s)
2 Voice FXS interface(s)
DRAM configuration is 64 bits wide with parity disabled.
125K bytes of non-volatile configuration memory.
16384K bytes of processor board System flash (Read/Write)
16384K bytes of processor board PCMCIA Slot0 flash (Read/Write)
Configuration register is 0x2102
MGCP_3640#sh diag
Slot 0:
Combo 2E, 2W Port adapter, 4 ports
Port adapter is analyzed
Port adapter insertion time unknown
EEPROM contents at hardware discovery:
Hardware revision 1.2
                            Board revision B0
Serial number 7687836 Part number 800-01171-04
                            RMA number
                                           00-00-00
Test history
                 0 \times 0
EEPROM format version 1
EEPROM contents (hex):
 0x20: 01 1E 01 02 00 75 4E 9C 50 04 93 04 00 00 00 00
 0x30: 58 00 00 00 98 02 28 17 FF FF FF FF FF FF FF FF
```

Cisco Systems, Inc.

Slot 1:



```
High Density Voice Port adapter
Port adapter is analyzed
Port adapter insertion time unknown
EEPROM contents at hardware discovery:
Hardware Revision : 1.1
Top Assy. Part Number : 800-03567-01
Top Assy. Full
Board Revision : F1
: Wimber : 0-0
Fab Version
                    : 02
                 : 00
PCB Serial Number
                    : JAB05080M1S
RMA Test History
RMA Number
                    : 0-0-0-0
RMA History
                     : 00
EEPROM format version 4
EEPROM contents (hex):
 0x00: 04 FF 40 00 CC 41 01 01 CO 46 03 20 00 0D EF 01
 0x10: 42 46 31 80 00 00 00 00 02 02 C1 8B 4A 41 42 30
 0x20: 35 30 38 30 4D 31 53 03 00 81 00 00 00 00 04 00
 WIC Slot 0:
E1 (2 Port) Multi-Flex Trunk WAN Daughter Card
Hardware revision 1.0 Board revision B0
Serial number 18779824 Part number 800-04479-01
              0x0 RMA number 00-00-00
Test history
Connector type PCI
EEPROM format version 1
EEPROM contents (hex):
  0x20: 01 23 01 00 01 1E 8E BO 50 11 7F 01 00 00 00
 0x30: 58 00 00 00 00 02 25 00 FF FF FF FF FF FF FF FF
HDV firmware: Compiled Fri 23-Mar-01 00:20 by miriyala
HDV memory size 524280 heap free 175065
Slot 2:
4 PORT Voice PM for MARs Port adapter
Port adapter is analyzed
Port adapter insertion time unknown
EEPROM contents at hardware discovery:
Hardware revision 1.1
                       Board revision CO
Serial number 10689987 Part number 800-02491-02
Test history
                        RMA number 00-00-00
EEPROM format version 1
EEPROM contents (hex):
 0x20: 01 65 01 01 00 A3 1D C3 50 09 BB 02 00 00 00 00
 0x30: 60 00 00 00 98 11 22 17 FF FF FF FF FF FF FF FF
WIC Slot 0:
FXS Voice daughter card (2 port)
Hardware revision 1.1 Board revision CO
Serial number 11291019 Part number 800-02493-01
Test history
              0x0
                        RMA number 00-00-00
Connector type Wan Module
```

Cisco Systems, Inc.



```
EEPROM format version 1
EEPROM contents (hex):
 0x20: 01 0E 01 01 00 AC 49 8B 50 09 BD 01 00 00 00
 0x30: 60 00 00 00 99 01 05 01 FF FF FF FF FF FF FF FF
WIC Slot 1:
FXO Voice daughter card (2 port)
Hardware revision 1.1
                      Board revision CO
Serial number 8421533
                      Part number 800-02495-01
Test history
              0x0 RMA number
                                   00-00-00
Connector type Wan Module
EEPROM format version 1
EEPROM contents (hex):
 0x20: 01 0D 01 01 00 80 80 9D 50 09 BF 01 00 00 00
 0x30: 60 00 00 00 98 06 02 01 FF FF FF FF FF FF FF FF
Slot 3:
High Density Voice Port adapter
Port adapter is analyzed
Port adapter insertion time unknown
EEPROM contents at hardware discovery:
Hardware Revision : 1.0
Top Assy. Part Number : 800-03567-01
Top Assy. 2012
Board Revision : AU : 0-0
                   : 02
Fab Version
PCB Serial Number
                 : JAB03350B9K
RMA Test History
                   : 00
RMA Number
                   : 0-0-0-0
RMA History
                    : 00
EEPROM format version 4
EEPROM contents (hex):
 0x00: 04 FF 40 00 CC 41 01 00 CO 46 03 20 00 0D EF 01
 0x10: 42 41 30 80 00 00 00 00 02 02 C1 8B 4A 41 42 30
 0x20: 33 33 35 30 42 39 4B 03 00 81 00 00 00 00 04 00
 WIC Slot 0:
T1 (2 Port) Multi-Flex Trunk (Drop&Insert) WAN Daughter Card
Hardware revision 1.0
                       Board revision A0
Serial number 19621702 Part number 800-04614-02
Test history
             0 \times 0
                       RMA number 00-00-00
Connector type PCI
EEPROM format version 1
EEPROM contents (hex):
 0x20: 01 24 01 00 01 2B 67 46 50 12 06 02 00 00 00 00
 0x30: 50 00 00 00 00 05 20 00 FF FF FF FF FF FF FF FF
HDV firmware: Compiled Fri 23-Mar-01 00:20 by miriyala
HDV memory size 524280 heap free 175065
MGCP_3640#sh controller e1
E1 1/0 is up.
```



```
Applique type is Channelized E1 - balanced
  No alarms detected.
  alarm-trigger is not set
  Version info Firmware: 20010315, FPGA: 15
  Framing is CRC4, Line Code is HDB3, Clock Source is Line.
  Data in current interval (11 seconds elapsed):
     O Line Code Violations, O Path Code Violations
     O Slip Secs, O Fr Loss Secs, O Line Err Secs, O Degraded Mins
     0 Errored Secs, 0 Bursty Err Secs, 0 Severely Err Secs, 0 Unavail Secs
  E1 1/1 is down.
  Applique type is Channelized E1 - balanced
  Far End Block Errors Detected
  Receiver has loss of signal.
  alarm-trigger is not set
  Version info Firmware: 20010315, FPGA: 15
  Framing is CRC4, Line Code is HDB3, Clock Source is Line.
  Data in current interval (12 seconds elapsed):
     O Line Code Violations, O Path Code Violations
     O Slip Secs, 12 Fr Loss Secs, O Line Err Secs, O Degraded Mins
     O Errored Secs, O Bursty Err Secs, O Severely Err Secs, 12 Unavail Secs
MGCP_3640# sh conf
Using 2266 out of 129016 bytes
!
version 12.2
no parser cache
no service single-slot-reload-enable
service timestamps debug uptime
service timestamps log uptime
no service password-encryption
no service dhcp
!
hostname MGCP_3640
logging rate-limit console 10 except errors
voice-card 1
voice-card 3
ip subnet-zero
no ip dhcp-client network-discovery
macp
mgcp call-agent 10.1.1.2 2427 service-type mgcp version 0.1
mgcp dtmf-relay voip codec all mode out-of-band
mgcp rtp unreachable timeout 1000 action notify
mgcp modem passthrough voip mode cisco
mgcp sdp simple
mgcp package-capability rtp-package
mgcp package-capability sst-package
no mgcp timer receive-rtcp
```



```
no mgcp explicit hookstate
isdn switch-type primary-ni
call rsvp-sync
ccm-manager mgcp
ccm-manager music-on-hold
ccm-manager config server 10.1.1.2
ccm-manager config
controller E1 1/0
pri-group timeslots 1-31 service mgcp
controller E1 1/1
controller T1 3/0
framing esf
linecode b8zs
pri-group timeslots 1-24 service mgcp
controller T1 3/1
framing sf
linecode ami
interface Ethernet0/0
ip address 10.1.1.200 255.255.255.0
no ip mroute-cache
half-duplex
interface Ethernet0/1
ip address 171.69.231.23 255.255.255.0
no ip mroute-cache
half-duplex
interface Serial1/0:15
no ip address
no logging event link-status
isdn switch-type primary-net5
isdn incoming-voice voice
isdn T310 4000
isdn bind-13 ccm-manager
no cdp enable
interface Serial3/0:23
no ip address
no logging event link-status
isdn switch-type primary-ni
isdn protocol-emulate network
 isdn incoming-voice voice
 isdn T306 30000
 isdn T310 40000
```



```
isdn bind-13 ccm-manager
no cdp enable
!
ip classless
no ip http server
snmp-server manager
voice-port 1/0:15
!
voice-port 2/0/0
!
voice-port 2/0/1
!
voice-port 2/1/0
!
voice-port 2/1/1
!
voice-port 3/0:23
!
dial-peer cor custom
dial-peer voice 1 pots
application mgcp
dial-peer voice 3 pots
application mgcpapp
port 2/0/1
dial-peer voice 2 pots
 application mgcpapp
port 2/0/0
dial-peer voice 999200 pots
application mgcpapp
port 2/0/0
dial-peer voice 9991015 pots
application mgcpapp
port 1/0:15
dial-peer voice 9993023 pots
application mgcpapp
port 3/0:23
line con 0
line aux 0
line vty 0 4
login
!
```



```
end
MGCP_3640#sh run
Building configuration...
Current configuration: 2266 bytes
version 12.2
no parser cache
no service single-slot-reload-enable
service timestamps debug uptime
service timestamps log uptime
no service password-encryption
no service dhcp
hostname MGCP_3640
logging rate-limit console 10 except errors
voice-card 1
voice-card 3
ip subnet-zero
no ip dhcp-client network-discovery
mgcp
mgcp call-agent 10.1.1.2 2427 service-type mgcp version 0.1
mgcp dtmf-relay voip codec all mode out-of-band
mgcp rtp unreachable timeout 1000 action notify
mgcp modem passthrough voip mode cisco
mgcp sdp simple
mgcp package-capability rtp-package
mgcp package-capability sst-package
no mgcp timer receive-rtcp
no mgcp explicit hookstate
isdn switch-type primary-ni
call rsvp-sync
ccm-manager mgcp
ccm-manager music-on-hold
ccm-manager config server 10.1.1.2
ccm-manager config
controller E1 1/0
pri-group timeslots 1-31 service mgcp
controller E1 1/1
```



```
controller T1 3/0
 framing esf
 linecode b8zs
pri-group timeslots 1-24 service mgcp
controller T1 3/1
 framing sf
linecode ami
interface Ethernet0/0
 ip address 10.1.1.200 255.255.255.0
 no ip mroute-cache
half-duplex
interface Ethernet0/1
 ip address 171.69.231.23 255.255.255.0
 no ip mroute-cache
half-duplex
interface Serial1/0:15
 no ip address
 no logging event link-status
 isdn switch-type primary-net5
 isdn incoming-voice voice
 isdn T310 4000
isdn bind-13 ccm-manager
no cdp enable
interface Serial3/0:23
no ip address
 no logging event link-status
 isdn switch-type primary-ni
 isdn protocol-emulate network
 isdn incoming-voice voice
 isdn T306 30000
 isdn T310 40000
isdn bind-13 ccm-manager
no cdp enable
ip classless
no ip http server
snmp-server manager
voice-port 1/0:15
voice-port 2/0/0
voice-port 2/0/1
voice-port 2/1/0
```



```
voice-port 2/1/1
!
voice-port 3/0:23
!
dial-peer cor custom
dial-peer voice 1 pots
application mgcp
dial-peer voice 3 pots
application mgcpapp
port 2/0/1
dial-peer voice 2 pots
application mgcpapp
port 2/0/0
dial-peer voice 999200 pots
application mgcpapp
port 2/0/0
dial-peer voice 9991015 pots
application mgcpapp
port 1/0:15
dial-peer voice 9993023 pots
application mgcpapp
port 3/0:23
line con 0
line aux 0
line vty 0 4
login
end
```


MGCP_3640#



Test Configuration

Figure 2
Test Topology

Basic Call Setup End-to-End Configuration



As shown in the diagram above, a NEC 2400 ICS PBX was connected via an ISDN E1 PRI link to a Cisco 3640 Gateway, which in turn, was connected to an Ethernet switch. The interoperability testing involved Layers 1, 2 and 3 on the ISDN PRI link between a Cisco 3640 and the PBX.

Layers 2 & 3 (Q.921 and Q.931)

Layer 2 and 3 packet exchanges were monitored using an Acacia Clarinet protocol analyzer, bridged across the PRI link in high impedance mode.

Layer 2 Q.921 packets were monitored to ensure that each PBX/3640 software configuration properly exchanged SABME/UA packets to initialize the ISDN link, and then RR packets were exchanged every 30 seconds.

Layer 3 Q.931 packets were monitored to ensure that the appropriate call setup/teardown packets were exchanged for each configuration, and that the SETUP packets contained the mandatory Information Elements with the necessary details, as well as optional IEs such as Calling Name and Number.

Telephone calls were made end-to-end in both directions through the Cisco 3640 Gateway, and a check was made to ensure that there was an audio path in both directions for each call.

User/Network Settings

The Cisco 3640 Gateway with ISDN protocol type setting of PRIMARY-NET5 supports both protocol sides by selecting "Network/User" in the protocol side field when configuring the Gateway via Callmanager.



Though the NEC 2400 ICS can be configured as either NETWORK (Master) or USER (Slave) side, configuration as NETWORK is not recommended. The NEC TAC center will not resolve a case presented with NEC set as the NETWORK side.

Test Results

Testing was performed by Test Engineer(s): Samir Batio and Bob Graves, March 11, 2002

Test Setup

Test configuration:

- PBX1 configured as ETSI, emulates Network
- Cisco 3640 Gateway configured as primary-net5, emulates User

Note: Configurations show PBX1 as Network with Cisco 3640 as User. Tests were actually performed both ways, but only the PBX-User results are provided because NEC does not officially support Network configuration.

Table 2 Test Setup Switch and Gateway Settings

NEC 2400 ICS Switch-type// Protocol -side Setting	Cisco 3640 ISDN Protocol-type/ Protocol-side Setting
ETSI/User	isdn switch-type primary-net5 isdn protocol-emulate Network

Table 3 Basic Calls: (Enbloc Sending)

Calls Made	Call Comp?	"Calling Number" Passed to Final Destination?	"Calling Name" Passed to Final Destination?	"Called Number" Passed to Orig. Side?	"Called Name" Passed to Orig. Side?	Notes
Phone A to Phone C	Yes	Yes	No	No	No	
Phone C to Phone A	Yes	Yes	No	Yes	No	



Table 4 Basic Calls: (FXS Port)

Calls Made	Call Comp?	"Number" Displayed on the digital phone?	"Name" Displayed on the digital phone?	Notes
Phone E to Phone A	Yes	Yes	No	
Phone A to Phone E	Yes	No	No	
Phone E to Phone C	Yes	Yes	Yes	
Phone C to Phone E	Yes	Yes	Yes	

 Table 5
 Call Transfers: (Supervised Local Transfers)

Calls Made	Call Comp?	Orig. "Calling Number" displayed on Final Dest. phone?	Orig. "Calling Name" displayed on Final Dest. phone?	"Called Number" display on Orig. phone updated after transfer?	"Called Name" display on Orig. phone updated after transfer?	Notes
Phone C to Phone A Xfr to Phone B	Yes	Yes	No	No	No	
Phone A to Phone C Xfr to Phone D	Yes	Yes	No	No	No	



Table 6 Call Conferencing (Local)

Calls Made	Call Comp?	"Calling Number" passed to remaining conferee when the conferencin g phone drops out?	"Calling Name" passed to remaining conferee when the conferencin g phone drops out?	"Connected Number" updated on Orig. Caller phone display when a conferee drops out?	"Connected Name" updated on Orig. Caller phone display when a conferee drops out?	Notes
Phone C to Phone A, Phone A conf Phone B	Yes	(A Drops out) Yes	(A Drops out) No	(A Drops out) No	(A Drops out) No	
Phone C to Phone A, Phone C conf Phone D	Yes	(C Drops out) No	(C Drops out) No	(D Drops out) No	(D Drops out) No	
Phone A to Phone C, Phone C conf Phone D	Yes	(C Drops out) No	(C Drops out) No	(C Drops out) No	(C Drops out) No	
Phone A to Phone C, Phone A conf Phone B	Yes	(A Drops out) No	(A Drops out) No	(B Drops out) No	(B Drops out) No	

Table 7 Call Forward (Local)

Calls Made	Call Comp?	Original "Calling Number" passed to Final Dest.?	Original "Calling Name" passed to Final Dest.?	Forwardi ng "Called Number" passed to Final Dest.?	Forwardi ng "Called Name" passed to Final Dest.?	Final dest. "Connec ted Number" updated at orig. side?	Final dest. "Connec ted Name" updated at orig. side?	Notes
Phone C to Phone A fwd to Phone B	Yes	Yes	No	Yes	No	No	No	
Phone A to Phone C fwd to Phone D	Yes	Yes	No	Yes	No	No	No	



Corporate Headquarters Cisco Systems, Inc. 170 West Tasman Drive San Jose, CA 95134-1706 USA www.cisco.com

Tel: 408 526-4000

Fax: 408 526-4100

800 553-NETS (6387)

European Headquarters Cisco Systems International BV Haarlerbergpark Haarlerbergweg 13-19 1101 CH Amsterdam The Netherlands www-europe.cisco.com

Tel: 31 0 20 357 1000 Fax: 31 0 20 357 1100 Americas Headquarters Cisco Systems, Inc. 170 West Tasman Drive San Jose, CA 95134-1706 USA

www.cisco.com Tel: 408 526-7660 Fax: 408 527-0883

Asia Pacific Headquarters Cisco Systems, Inc. Capital Tower 168 Robinson Road #22-01 to #29-01 Singapore 068912 www.cisco.com

Tel: +65 317 7777 Fax: +65 317 7799

Cisco Systems has more than 200 offices in the following countries and regions. Addresses, phone numbers, and fax numbers are listed on the Cisco Web site at www.cisco.com/go/offices

Argentina • Australia • Australia • Belgium • Brazil • Bulgaria • Canada • Chile • China PRC • Colombia • Costa Rica • Croatia Czech Republic • Denmark • Dubai, UAE • Finland • France • Germany • Greece • Hong Kong SAR • Hungary • India • Indonesia • Ireland Israel • Italy • Japan • Korea • Luxembourg • Malaysia • Mexico • The Netherlands • New Zealand • Norway • Peru • Philippines • Poland Portugal • Puerto Rico • Romania • Russia • Saudi Arabia • Scotland • Singapore • Slovakia • Slovenia • South Africa • Spain • Sweden Switzerland · Taiwan · Thailand · Turkey · Ukraine · United Kingdom · United States · Venezuela · Vietnam · Zimbabwe

All contents are Copyright © 1992-2002, Cisco Systems, Inc. All rights reserved. CCIP, the Cisco Arrow logo, the Cisco Powered Network mark, the Cisco Systems Verified logo, Cisco Unity, Follow Me Browsing, FormShare, Internet Quotient, iQ Breakthrough, iQ Expertise, iQ FastTrack, the iQ logo, iQ Net Readiness Scorecard, Networking Academy, ScriptShare, SMARTnet, TransPath, and Voice LAN are trademarks of Cisco Systems, Inc.; Changing the Way We Work, Live, Play, and Learn, Discover All That's Possible, The Fastest Way to Increase Your Internet Quotient, and iQuick Study are service marks of Cisco Systems, Inc.; and Aironet, ASIST, BPX, Catalyst, CCDA, CCDP, CCIE, CCNA, CCNP, Cisco, the Cisco Certified Internetwork Expert logo, Cisco IOS, the Cisco IOS logo, Cisco Press, Cisco Systems, Cisco Systems Capital, the Cisco Systems logo, Empowering the Internet Generation, Enterprise/Solver, EtherChannel, EtherSwitch, Fast Step, GigaStack, IOS, IP/TV, LightStream, MGX, MICA, the Networkers logo, Network Registrar, Packet, PIX, Post-Routing, Pre-Routing, RateMUX, Registrar, SlideCast, StrataView Plus, Stratm, SwitchProbe, TeleRouter, and VCO are registered trademarks of Cisco Systems, Inc. and/or its affiliates in the U.S. and certain other countries.

All other trademarks mentioned in this document or Web site are the property of their respective owners. The use of the word partner does not imply a partnership relationship between Cisco and any other company.