Numerics

2.5-Gbps line card motherboards
- cabling 2-42
- direct connections 2-40
- installing 2-19

2.5-Gbps transponder modules
- configuring interfaces 3-12
- configuring splitter protection 3-26
- configuring y-cable protection 3-27
- verifying client signal power level 4-18
- verifying laser frequency 4-13
- verifying optical transmission quality 4-23

4-channel mux/demux modules
- installing 2-17
- optical link loss for data channels (table) 4-17
- optical link loss for OSC (table) 4-18

8-channel mux/demux modules
- installing 2-17
- optical link loss for data channels (table) 4-17
- optical link loss for OSC (table) 4-18

10-Gbps line card motherboards
- cross connect drawers 2-52
- direct connections 2-47
- installing 2-20
- y cables 2-49

10-Gbps transponder modules
- configuring y-cable protection 3-27

10-GE transponder modules
- configuring interfaces 3-15
- configuring splitter protection 3-26
- installing 2-23
- verifying client signal power level 4-22
- verifying optical transmission quality 4-25

32-channel mux/demux modules
- installing 2-17
- optical link loss for data channels (table) 4-18
- optical link loss for OSC (table) 4-18

A

AC power
- installing 2-63

AC power shelf
- installing 2-57

alarms
- verifying generation 4-27

APS
- configuring 3-25 to 3-30
- verifying configuration 5-8
- verifying splitter operation 5-9
- verifying trunk fiber protection operation 5-11
- verifying y-cable operation 5-10

aps direction command 3-30
aps disable command 3-30
aps enable command 3-27, 3-28, 3-29, 3-30
aps message-channel command 3-29
aps protection command 3-26, 3-28, 3-29
aps working command 3-26, 3-28, 3-29
aps y-cable command 3-28
associate group command 3-26, 3-28, 3-29, 3-30

B

BER tests
verifying 5-5
bidirectional path switch
configuring 3-29

C

cabling
2.5-Gbps line card motherboards 2-42
10-Gbps line card motherboards 2-47
auxiliary ports 2-28
cable storage drawers 2-32
console ports 2-27
cross connect drawers 2-52
mux/demux modules 2-34, 2-36, 2-40, 2-47, 2-52
NME ports 2-27
options 2-28
OSC 2-34
PSMs 2-36
PSMs (figure) 2-37
requirements 1-5
selecting 2-28
transponder modules 2-39
y cables 2-49
CDP
verifying connectivity 5-4
chassis
safety precautions 1-3
cleaning
2.5 Gbps kit 1-11
10-GE kit 1-11
cartridges 1-11
information 1-8
kits 1-11
optical connectors 2-31
procedures 1-8
clock rate command 3-13
clock set command 3-6
clock summer-time date command 3-7
clock summer-time recurring command 3-7
clock timezone command 3-6
connections
cleaning 2-31
DC power 2-59
external power shelf 2-65
inspecting 1-13
cross connect drawers
cabling 2-42
using 2-52
cross connections
verifying status 4-11

D

data channels
optical link loss through 32-channel mux/demux modules 4-18
duplex command 3-4

E

electrostatic discharge 1-4
enable password command 3-3
enable passwords
configuring 3-2
enable secret command 3-3
encapsulation command 3-13
equipment
cables 1-4
grounding 2-55
inspection 1-9
system 1-4
test 1-4
ESCON
configuring protocol encapsulation (table) 3-13

ESD
precautions 1-2
preventing damage 1-4

F

Fast Ethernet
configuring protocol encapsulation (table) 3-13
fastethernet 0 interfaces
configuring IP address 3-4
FDDI
configuring protocol encapsulation (table) 3-13
fiber
characterization 1-8
Fibre Channel
configuring protocol encapsulation (table) 3-13
FICON
configuring protocol encapsulation (table) 3-13
frequency
verifying 4-15 to 4-22

G

Gigabit Ethernet
configuring protocol encapsulation (table) 3-13
grounding
procedure 2-55
shelf 2-55

H

host name
configuring 3-5
hostname command 3-5

I

installing
2.5-Gbps line card motherboards 2-19
4-channel mux/demux modules 2-17
8-channel mux/demux modules 2-17
10-Gbps line card motherboards 2-20
10-GE transponder modules 2-23
32-channel mux/demux modules 2-17
AC power shelf 2-57
cable management drawer 2-6
cable management system 2-4
chassis 2-2
cross connect panel 2-7
external AC power supply 2-63
external power shelf 2-58
mux/demux motherboards 2-15
processor cards 2-13
PSMs 2-18
redundant processor cards 2-15
SFP optics 2-25
Type 1 MM transponder modules 2-22
Type 1 SM transponder modules 2-21
Type 2 extended range transponder modules 2-24
vertical cable guides 2-10
interface loopback command 3-8
interfaces
configuring 3-12 to 3-18
verifying status 4-2 to 4-11
interface transparent command 3-14
IP access
configuring NME interfaces 3-4
configuring on NME 3-4
configuring on OSC using loopback interface 3-8
ip address command 3-4, 3-8
ip default-gateway command 3-5
ip route command 3-9
ip unnumbered command 3-8

L

laser frequency
  verifying 4-12 to 4-14
laser frequency command 3-14
lasers
  safety warning 1-3
line card motherboards
  optical link loss (table) 4-17
logging
  configuring time stamps 3-6

M

management access
  configuring 3-2 to 3-11
modules
  handling precautions 1-2
mux/demux motherboards
  installing 2-15

N

network information
  record A-1
network testing
  verifying optical budget between nodes 5-2
  verifying power levels 5-4
network topology
  verifying neighbor connectivity 5-4
NME interfaces
  configuring IP access 3-4
node information
  record A-1
no laser shutdown command 3-15

O

OFC
  configuring with encapsulation command 3-13
optical budget
  verifying 5-2
optical power
  verifying 4-15 to 4-22
optical signal
  verifying transmission quality 4-23 to 4-27
optical signal protection
  verifying configuration and operation 5-8 to 5-12
See also APS
optical spectrum analyzer. See OSA
optical threshold power receive command 3-17
OSA
  measuring optical power 5-2
OSC
  cabling 2-35
  configuring IP access 3-8 to 3-11
  connecting 2-34
  optical link loss through mux/demux modules 4-18
  verifying connectivity 5-3

P

passwords
  configuring enable passwords 3-2
  configuring secret enable passwords 3-3
patch command 3-24
patch connections
  configuring 3-18 to 3-25
  types (table) 3-19
patches
  verifying configuration 4-11
path switching
  configuring 3-29

power
connecting external power 2-65
DC power 2-59
DC protection 1-2
install external AC power 2-63
installing AC 2-57
installing external 2-58
procedure 2-57
power levels
verifying 5-4
processor cards
installing 2-13
verifying redundancy status 4-28
PSMs
cabling 2-36
configuring interfaces 3-17
configuring trunk fiber based protection 3-28
installing 2-18

R

redundancy
verifying status 4-28
redundancy command 3-26, 3-28, 3-30
redundant processor cards
installing 2-15
router bgp command 3-9
router eigrp command 3-9
router ospf command 3-9

S

safety
information 1-1
reference 1-1
warnings 1-1
SDH
configuring protocol encapsulation (table) 3-13
secret enable passwords
configuring 3-3
service timestamps log command 3-7
SFP optics
details 1-5
installing 2-25
show hardware command 2-66
SNMP
configuring 3-30
snmp-server enable traps command 3-31
snmp-server host command 3-31
software setup
verifying configuration 3-31
SONET
configuring protocol encapsulation (table) 3-13
speed command 3-4
splitter protection
configuring 3-26
verifying configuration 5-8
verifying operation 5-9
Synchronous Digital Hierarchy. See SDH
system time
configuring 3-6

T

test results
table B-1
time zone
configuring 3-6
topology neighbor agent ip-address command 3-17, 3-18
topology neighbor command 3-13, 3-15, 3-17, 3-18
transmission
verifying quality 5-5
trunk fiber based protection
configuring wdmsplit interfaces 3-28
verifying operation 5-11
trunk signal
verifying power level 4-15

Type 1 MM transponder modules
installing 2-22
Type 1 SM transponder modules
installing 2-21
Type 2 extended range transponder modules
installing 2-24
LEDs (table) 2-25

U

unidirectional path switching
configuring 3-29

V

verifying
fiber characteristics 1-8
hardware installation 2-66
power up 2-66

W

wavelengths
BER testing 5-5
mapped to channels (table) 4-14
wdmsplit interface
enabling 3-17

Y

y-cable line card protection
configuring 3-27
verifying configuration 5-8
verifying operation 5-10
y cables
10-Gbps line card motherboards 2-49
options 2-31