



## New CLEI Label for Cisco 6260 PEMs

---

**July 10, 2000**

The CLEI code labels on one or more Cisco 6260 power entry modules (PEMs) at your site may contain an error. This package contains corrected replacement labels. This document tells you how to attach the label(s) to the hardware.

The Common Language Equipment Identifier (CLEI) code on the label is a tracking tool for maintenance and inventory. If you use CLEI codes to track equipment, it is important that you put the corrected labels on your PEMs.


The error is found on Cisco 6260 PEMs shipped before June 1, 2000. On the affected CLEI labels, the first letter of the CLEI code is wrong:

Incorrect CLEI code    BMP1D00CAA

Correct CLEI code     DMP1D00CAA

- 
- Step 1**    Check the CLEI codes on all Cisco 6260 PEMs at your site. The PEMs are located at the bottom of the Cisco 6260 chassis, facing forward. The CLEI label is located on the front left corner of each PEM.
- Step 2**    Attach a new CLEI label to any PEM whose CLEI label is incorrect. Apply the new label so that it covers the old one. See [Figure 1](#).
-

Figure 1 Applying the New CLEI Label



You can find the most current documentation on Cisco Connection Online (CCO). These electronic documents may contain updates made after the hard copy documents were printed. You can access CCO in the following ways:

- WWW: <http://www.cisco.com>
- WWW: <http://www-europe.cisco.com>
- WWW: <http://www-china.cisco.com>
- Telnet: [cco.cisco.com](http://cco.cisco.com)
- Modem: From North America, 408 526-8070; from Europe, 33 1 64 46 40 82. Use the following terminal settings: VT100 emulation; databits: 8; parity: none; stop bits: 1; and connection rates up to 28.8 kbps.



Note

If you are a network administrator and need personal technical assistance with a Cisco product that is under warranty or covered by a maintenance contract, contact the Cisco Technical Assistance Center (TAC) at 800 553-2447, 408 526-7209, or [tac@cisco.com](mailto:tac@cisco.com). To obtain general information about Cisco Systems, Cisco products, or upgrades, contact 800 553-6387, 408 526-7208, or [cs-rep@cisco.com](mailto:cs-rep@cisco.com).

CCIP, the Cisco Arrow logo, the Cisco Powered Network mark, the Cisco Systems Verified logo, Cisco Unity, Follow Me Browsing, FormShare, Internet Quotient, iQ Breakthrough, iQ Expertise, iQ FastTrack, the iQ Logo, iQ Net Readiness Scorecard, Networking Academy, ScriptShare, SMARTnet, TransPath, and Voice LAN are trademarks of Cisco Systems, Inc.; Changing the Way We Work, Live, Play, and Learn, Discover All That's Possible, The

Contact Us to Increase Your Internet Quotient, and iQuint Study are service marks of Cisco Systems, Inc. and Cisco. A CIST DDV Catalyst CCNA  
Copyright © 2002, Cisco Systems, Inc.  
All rights reserved.