



Supported Devices for CWSI Campus 2.3

Revised: June 7, 2002

The following table lists supported devices for CWSI Campus 2.3:

Routers	Devices Supported	Topology	Cisco View	Traffic Director	Vlan Director	Lane Mgmt	Atm Director	User Tracking	Minimum Software
Cisco Universal Broadband Routers	UBR7223, UBR7246	Not Tested	Not Tested	Limited Support ¹	Not Tested	Not Tested	Not Tested	Not Tested ²	IOS 11.0 ⁴
Cisco 7000 Series	7000, 7010, 7202, 7204, 7206, 7505, 7507, 7513	Supported	Supported	Limited Support ¹	Not Applicable	Supported	Supported	Supported ²	IOS 11.1
Cisco 4000 Series	4000, 4000-M, 4500, 4500-M, 4700, 4700-M	Supported	Supported	Limited Support ¹	Not Applicable	Supported ³	Supported ³	Supported ²	IOS 11.0 ⁴
Cisco switching access concentrator	MC3810	Supported	Supported	Not Applicable	Not Applicable	Not Applicable	Not Applicable	Not Applicable	IOS 11.0 ⁴
Cisco 3600 Series	3620, 3640	Supported	Supported	Limited Support ¹	Not Applicable	Not Supported	Not Supported	Supported ²	IOS 11.3
Cisco 2600 Series	2601, 2610, 2611, 2612, 2620, 2621	Supported: All but 2601	Supported	Limited Support ¹	Not Applicable	Not Applicable	Not Applicable	Supported: All but 2601 ²	IOS 11.3
Cisco 2500 Series	2500-2525, 2501CF, 2502CF, 2501LF, 2502LF	Supported	Supported	Limited Support ¹	Not Applicable	Not Applicable	Not Applicable	Supported ²	IOS 11.0 ⁴
Cisco 1700 Series	1720 VPN	Supported	Supported	Limited Support ¹	Not Applicable	Not Applicable	Not Applicable	Supported ²	IOS 12.0

Cisco 1600 Series	1601, 1602, 1603, 1604, 1605	Supported	Supported	Limited Support ¹	Not Applicable	Not Applicable	Not Applicable	Supported ²	IOS 11.2
Cisco 1000 Series	1000, 1003, 1004, 1005, 1020	Supported	Supported	Limited Support ¹	Not Applicable	Not Applicable	Not Applicable	Supported ²	IOS 11.0 ⁴
Cisco 800 Series	801-804	Supported	Supported	Limited Support ¹	Not Applicable	Not Applicable	Not Applicable	Supported ²	IOS 12.0
Cisco 700 Series	761, 762, 765, 766, 771, 772, 775, 776	Not Supported	Supported	Not Applicable	Not Applicable	Not Applicable	Not Applicable	Not Applicable	4.1
Access Servers	Devices Supported	Topology	Cisco View	Traffic Director	Vlan Director	Lane Mgmt	Atm Director	User Tracking	Minimum Software
Cisco AS5000 Series Access Servers	AS5800, AS5300, AS5200	Supported	Supported	Not Applicable	Not Applicable	Not Applicable	Not Applicable	Not Applicable	IOS 11.0 ⁴
Cisco 2500 Series Access Servers	2511RJ, 2509RJ	Supported	Supported	Not Applicable	Not Applicable	Not Applicable	Not Applicable	Not Applicable	IOS 11.0 ⁴
Switches	Devices Supported	Topology	Cisco View	Traffic Director	Vlan Director	Lane Mgmt	Atm Director	User Tracking	Minimum Software
Catalyst 8500 MSR Series	8510 MSR, 8540 MSR	Supported	Supported ⁵	Supported	Not Applicable	Supported	Supported	Not Applicable	IOS 11.2 (8.0.1) FWA4.1
Lightstream Series	LightStream 1010	Supported	Supported	Not Supported	Not Applicable	Supported	Supported	Not Applicable	IOS 11.2 (8.0.1) FWA4.1
Multiservice switch	BPX 8620, BPX 8650, IGX 8410, IGX 8420, IGX 8430, MGX 8220, IPX 8xxx	Not Supported	Supported ⁶	Not Supported	Not Applicable	Not Supported	Not Supported	Not Applicable	8.4
Catalyst 8500 CSR Series	8510 CSR, 8540 CSR	Supported	Supported	Supported	Not Applicable	Not Applicable	Not Applicable	Supported	IOS 11.3
Catalyst 6000 Series	6006, 6009, 6506, 6509	Supported	Supported	Supported	Supported	Not Applicable	Not Applicable	Supported	5.1(1)CSX
Catalyst 6000 Series	WS-X6302	Supported	Supported	Limited Support ¹	Not Applicable	Not Applicable	Not Applicable	Supported	IOS 12.0
Catalyst 5000 Series	5000, 5002, 5500, 5505, 5509	Supported ⁷	Supported	Supported	Supported ⁷	Supported	Supported ⁷	Supported	2.4.3

Catalyst 5000 Series	WS-X5302	Supported	Supported	Limited Support ¹	Not Applicable	Not Applicable	Not Applicable	Supported	IOS 12.0
Catalyst 4000 Series	4003, 4912G	Supported	Supported	Supported	Supported	Not Applicable	Not Applicable	Supported	4.4(1)
Catalyst 3900 Series	3900, 3920	Supported	Supported	Supported	Supported	Not Supported	Supported	Supported	3.0(2)
Catalyst 3000	3000, 3100, 3200	Supported	Supported	Supported	Supported	Supported	Supported	Supported	2.2.2
Catalyst 2900 Series	2901, 2902, 2926, 2926G, 2948G	Supported	Supported	Supported	Supported	Not Applicable	Not Applicable	Supported	2.4.3, [2926G 4.3(0.31)], [2948G 4.4(1)]
Catalyst 2900XL Series	2908XL, 2916M-XL, 2924XL-V, 2924C-XL-V, 2912XL, 2924M-XL, 2912MF-XL, 2924XL, 2924C-XL	Supported	Supported	Supported	Supported	Not Applicable	Not Applicable	Supported	IOS 11.2 (8) SA5
Catalyst 2800 Series	2822, 2828	Supported	Supported	Supported	Supported	Supported	Supported	Supported	8.0 (Enterprise)
Catalyst 1900 Series	1912, 1924	Supported	Supported	Supported	Supported	Not Applicable	Not Applicable	Supported	8.0 (Enterprise)
Catalyst 1200 Series	1201, 1202, 1211, 1212	Supported	Supported	Supported	Not Supported	Not Applicable	Not Applicable	Not Supported	4.29
SwitchProbe and Network Analysis Modules									
	Devices Supported	Topology	Cisco View	Traffic Director	Vlan Director	Lane Mgmt	Atm Director	User Tracking	Minimum Software
LAN SwitchProbes	Ethernet, Token Ring, FDDI, Fast Ethernet	Not Supported	Not Supported	Supported	Not Supported	Not Supported	Not Supported	Not Supported	4.2.1
WAN SwitchProbes	FR, ATM, HSSI	Not Supported	Not Supported	Supported	Not Supported	Not Supported	Not Supported	Not Supported	4.2.1
WAN SwitchProbes	Multi-port WAN	Not Supported	Not Supported	Supported	Not Supported	Not Supported	Not Supported	Not Supported	4.2.2
Network Analysis Module	Catalyst 5000 module	Not Applicable	Supported	Supported	Not Applicable	Not Applicable	Not Applicable	Not Applicable	4.3 (Catalyst)

¹ TrafficDirector supports Cisco-IOS-based RMON devices. Two group RMON support (that is, Alarms and Events) is provided in IOS versions 11.1. Full RMON support (all 9 groups) is provided as an option in the IOS 11.1 Plus and greater images for the 2500 family routers and the AS5200 and AS5300 access servers.

- 2 Cisco routers supply the UserTracking application with ARP table information.
- 3 Provided only on the 4500 and 4700 series.
- 4 IOS 10.3 may work, however it is not Year 2000 compliant.
- 5 A CiscoView package for the 8510 MSR will be available in May, 1999.
- 6 Tested only on Solaris and AIX.
- 7 IOS versions 3.2(7), 3.2(9), and 3.2(12) are compatible code bases for Catalyst 5000 ATM interfaces.